

Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING

FLUID PYPSF32

# 1. IDENTIFICATION OF THE SUBSTANCE/MIXTURE AND OF THE COMPANY/UNDERTAKING

Ashland Regulatory Information Number 1-800-325-3751
P.O. Box 2219 Telephone 614-790-3333
Columbus, OH 43216 Emergency telephone 1-800-ASHLAND (1-800-274-5263)

Product name PYROIL® POWER STEERING FLUID

Product code PYPSF32
Product Use Description No data

## 2. HAZARDS IDENTIFICATION

## **Emergency Overview**

Appearance: liquid, amber

CAUTION! PROLONGED OR REPEATED CONTACT MAY DRY SKIN AND CAUSE IRRITATION.

#### **Potential Health Effects**

#### **Exposure routes**

Inhalation, Skin Absorption, Skin contact, Eye Contact, Ingestion

## **Eve contact**

May cause mild eye irritation. Symptoms include stinging, tearing, and redness.

#### Skin contact

May cause mild skin irritation. Prolonged or repeated contact may dry the skin. Symptoms may include redness, burning, drying and cracking of skin, and skin burns.

# Ingestion

Swallowing small amounts of this material during normal handling is not likely to cause harmful effects. Swallowing large amounts may be harmful.

#### Inhalation

It is possible to breathe this material under certain conditions of handling and use (for example, during heating, spraying, or stirring). Breathing small amounts of this



Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING FLUID PYPSF32

material during normal handling is not likely to cause harmful effects. Breathing large amounts may be harmful. Symptoms are not expected at air concentrations below the recommended exposure limits, if applicable (see Section 8.).

# **Aggravated Medical Condition**

Preexisting disorders of the following organs (or organ systems) may be aggravated by exposure to this material:, Skin

# **Symptoms**

Signs and symptoms of exposure to this material through breathing, swallowing, and/or passage of the material through the skin may include:, stomach or intestinal upset (nausea, vomiting, diarrhea), irritation (nose, throat, airways), Abdominal pain

#### **Target Organs**

No data

#### Carcinogenicity

This material is not listed as a carcinogen by the International Agency for Research on Cancer (IARC), the National Toxicology Program (NTP), or the Occupational Safety and Health Administration (OSHA). Used motor oil has been shown to cause skin cancer in laboratory animals continually exposed by repeated applications. Avoid prolonged or repeated skin contact.

#### Reproductive hazard

Based on the available information, risk to the fetus from maternal exposure to this material cannot be assessed.

## 3. COMPOSITION/INFORMATION ON INGREDIENTS

Components	CAS-No.	Concentration
PETROLEUM DISTILLATES	NJTS# 800986-5245P	>=90-<=100%

## 4. FIRST AID MEASURES

#### Eyes



Page: 3 Revision Date: 11/12/2009

Print Date: 1/22/2010

MSDS Number: R0177840 Version: 3.8

PYROIL® POWER STEERING FLUID PYPSF32

If symptoms develop, immediately move individual away from exposure and into fresh air. Flush eyes gently with water for at least 15 minutes while holding eyelids apart; seek immediate medical attention.

#### Skin

First aid is not normally required. However, it is recommended that exposed areas be cleaned by washing with soap and water.

# Ingestion

Seek medical attention. If individual is drowsy or unconscious, do not give anything by mouth; place individual on the left side with the head down. Contact a physician, medical facility, or poison control center for advice about whether to induce vomiting. If possible, do not leave individual unattended.

#### Inhalation

If symptoms develop, move individual away from exposure and into fresh air. If symptoms persist, seek medical attention. If breathing is difficult, administer oxygen. Keep person warm and quiet; seek immediate medical attention.

#### Notes to physician

Hazards: Acute aspiration of large amounts of oil-laden material may produce a serious aspiration pneumonia. Patients who aspirate these oils should be followed for the development of long-term sequelae. Repeated aspiration of small quantities of mineral oil can produce chronic inflammation of the lungs (i.e. lipoid pneumonia) that may progress to pulmonary fibrosis. Symptoms are often subtle and radiological changes appear worse than clinical abnormalities. Occasionally, persistent cough, irritation of the upper respiratory tract, shortness of breath with exertion, fever, and bloody sputum occur. Inhalation exposure to oil mists below current workplace exposure limits is unlikely to cause pulmonary abnormalities.

**Treatment:** No information available.

## **5. FIRE-FIGHTING MEASURES**

# Suitable extinguishing media

Carbon dioxide (CO2), Dry chemical, Foam

#### **Hazardous combustion products**

carbon dioxide and carbon monoxide, oxides of sulfur, nitrogen and phosphorus, Hydrocarbons



Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING FLUID PYPSF32

# **Precautions for fire-fighting**

Never use welding or cutting torch on or near drum (even empty) because product (even just residue) can ignite explosively. During a fire, irritating or toxic decomposition products may be generated. Wear full firefighting turn-out gear (full Bunker gear), and respiratory protection (SCBA). DO NOT direct a solid stream of water or foam into hot, burning pools of liquid since this may cause frothing and increase fire intensity. Frothing can be violent and possibly endanger any firefighter standing too close to the burning liquid.

#### Flammability Class for Flammable Liquids

Combustible Liquid Class IIIB

## 6. ACCIDENTAL RELEASE MEASURES

## **Personal precautions**

No data

## **Environmental precautions**

No data

#### Methods for cleaning up

Persons not wearing protective equipment should be excluded from area of spill until clean-up has been completed. Stop spill at source, dike area of spill to prevent spreading, pump liquid to salvage tank. Remaining liquid may be taken up on sand, clay, earth, floor absorbent, or other absorbent material and shoveled into containers.

#### Other information

Notify the proper authorities as required that a spill has occurred. Comply with all applicable federal, state, and local regulations.

# 7. HANDLING AND STORAGE

#### Handling

Containers of this material may be hazardous when emptied. Since emptied containers retain product residues (vapor, liquid, and/or solid), all hazard precautions given in the data sheet must be observed.



Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING

FLUID PYPSF32

# **Storage**

Keep containers closed when not in use.

## 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

# **Exposure Guidelines**

#### AROMATIC HYDROCARBON AROMATIC HYDROCARBON

OSHA Z1	Permissible exposure limit	500 ppm	
OSHA Z1	Permissible exposure limit 2,000 mg/m3		
OSHA Z1A	time weighted average	ed average 400 ppm	
OSHA Z1A	time weighted average 1,600 mg/m3		
US CA OEL	Time Weighted Average (TWA)	A) 400 ppm	
	Permissible Exposure Limit (PEL):		
US CA OEL	Time Weighted Average (TWA)	1,600 mg/m3	
	Permissible Exposure Limit (PEL):		
ACGIH	time weighted average	5 mg/m3	Mist.
ACGIH	Short term exposure limit	10 mg/m3	Mist.
ACGIH NIC	time weighted average	0.2 mg/m3	Inhalable fraction.

#### General advice

These recommendations provide general guidance for handling this product. Personal protective equipment should be selected for individual applications and should consider factors which affect exposure potential, such as handling practices, chemical concentrations and ventilation. It is ultimately the responsibility of the employer to follow regulatory guidelines established by local authorities.

## **Exposure controls**

General room ventilation should be adequate for normal conditions of use. However, if unusual operating conditions exist, provide sufficient mechanical (general



Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING FLUID

and/or local exhaust) ventilation to maintain exposure below exposure guidelines (if applicable) or below levels that cause known, suspected or apparent adverse effects.

## **Eye protection**

PYPSF32

Not required under normal conditions of use. Wear splash-proof safety goggles if material could be misted or splashed into eyes.

## Skin and body protection

Not normally required. However, wear resistant gloves such as nitrile rubber to prevent irritation which may result from prolonged or repeated skin contact with product. Wear normal work clothing including long pants, long-sleeved shirts and foot covering to prevent direct contact of the product with the skin. Launder clothing before reuse. If skin irritation develops, contact your facility health and safety professional or your local safety equipment supplier to determine the proper personal protective equipment for your use.

# Respiratory protection

Respiratory protection is not required under normal conditions of use.

## 9. PHYSICAL AND CHEMICAL PROPERTIES

Physical stateliquidFormNo dataColouramberOdourNo data

**Boiling point/boiling range** 218.33 °C / 424.99 °F@ 1,013.33 hPa

**pH** No data

**Flash point** 347.00 °F / 175.00 °C, Open Cup

**Evaporation rate** > 1 (Ethyl Ether)

Explosion limitsNo dataVapour pressure0.00 hPaVapour densityNo dataDensity0.87 g/cm3

7.2200 lb/gal @ 60.00 °F / 15.56 °C

**Solubility** No data **Partition coefficient: n-** No data

octanol/water

log Pow no data available



Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING FLUID

PYPSF32

**Autoignition temperature** 

No data

# 10. STABILITY AND REACTIVITY

## **Stability**

Stable.

# **Conditions to avoid**

Heat, flames and sparks.

# **Incompatible products**

Strong oxidizing agents

# Hazardous decomposition products

carbon dioxide and carbon monoxide, oxides of sulfur, nitrogen and phosphorus, Hydrocarbons

#### **Hazardous reactions**

Product will not undergo hazardous polymerization.

# Thermal decomposition

No data

# 11. TOXICOLOGICAL INFORMATION

## **Acute oral toxicity**

PETROLEUM DISTILLATES	LD 50 Rat: > 5.000 mg/kg

# Acute inhalation toxicity \_\_\_\_\_

## **Acute dermal toxicity**

PETROLEUM DISTILLATES	LD 50 Rabbit: > 5,000 mg/kg

# 12. ECOLOGICAL INFORMATION

## **Aquatic toxicity**



Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING FLUID PYPSF32

> Acute and Prolonged Toxicity to Fish No data Acute Toxicity to Aquatic Invertebrates No data

# **Environmental fate and pathways**

No data

## 13. DISPOSAL CONSIDERATIONS

#### Waste disposal methods

For assistance with your waste management needs - including disposal, recycling and waste stream reduction, contact Ashland Distribution's Environmental Services Group at 800-637-7922.

## 14. TRANSPORT INFORMATION

Dangerous goods descriptions (if indicated above) may not reflect quantity, end-use or region-specific exceptions that can be applied. Consult shipping documents for descriptions that are specific to the shipment.

## 15. REGULATORY INFORMATION

#### California Prop. 65

Proposition 65 warnings are not required for this product based on the results of a risk assessment.

SARA Hazard Classification Acute Health Hazard

New Jersey RTK Label Information PETROLEUM DISTILLATES AROMATIC HYDROCARBON

NJTS 800986-5245P

Pennsylvania RTK Label Information



Revision Date: 11/12/2009

Print Date: 1/22/2010 MSDS Number: R0177840

Version: 3.8

PYROIL® POWER STEERING

FLUID PYPSF32

PETROLEUM DISTILLATES AROMATIC HYDROCARBON

NJTS 800986-5245P

**Reportable quantity - Components** 

PETROLEUM DISTILLATES NJTS# 800986-5245P none

	Health	Flammability	Reactivity	Other
HMIS	1	1	0	
NFPA	1	1	0	

## 16. OTHER INFORMATION

The information accumulated herein is believed to be accurate but is not warranted to be whether originating with the company or not. Recipients are advised to confirm in advance of need that the information is current, applicable, and suitable to their circumstances. This MSDS has been prepared by Ashland's Environmental Health and Safety Department (1-800-325-3751).